

JAMES E. RISCH -- Governor RICHARD M. ARMSTRONG -- Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

November 20, 2006

Larue Gunter, Administrator Crystal Springs Living Center 8284 S Crystal Springs Rd Mc Cammon, ID 83250 FILE COPY

License #: RC-510

Dear Ms. Gunter:

On September 20, 2006, a life safety code survey was conducted at Crystal Springs Living Center. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

EM/slc



JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 5, 2006

Larue Gunter, Administrator Crystal Springs Living Center 8284 S Crystal Springs Rd Mc Cammon, ID 83250 FILE COPY

Dear Ms. Gunter:

On September 20, 2006, a life safety code survey was conducted at Crystal Springs Living Center. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by October 20, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

<u>Dureau (</u>	JI Facility Standards	·						
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - ENTIRE BUILDINGQ B. WING		(X3) DATE SURVEY COMPLETED 09/20/2006		
NAME OF P	ROVIDER OR SUPPLIER		STREET AD	DRESS, CITY, ST	ATE, ZIP CODE		***************************************	
COVETAL EDDINGS LIVING CENTED 8284 S C				RYSTAL SPRINGS RD MON, ID 83250				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG			(X5) COMPLETE DATE	
R 000	compliance with the requirements of the Assisted Living Factoric deficiencies were of fire/life safety surve 20, 2006.	/eyor	al or ore ard tember	R 000				
			ŀ					

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

		V .	(208) 334-6626 fax: (208) 364-1666	T UTION LIST					
Facility Name			Physical Address	Phone Number					
Constal	Spring Li	ing Centin	8284 South Cogated Sprs Rd	254 9279					
Administrator	- P - P -		City	ZIP Code					
(arre	Grunter		McCamman	83250					
Survey Team Leader			Survey Type	Survey Date					
Evil V	mundell'		Fin / Libe Safetly	9/20/06					
NON-CORE ISSU									
ITEM RU	LE#	read of the court of the a	DESCRIPTION	DATE RESOLVED					
	2.405,01.6 Elec	Vical Equipr	not: Extension cord and multi	de cuffet/					
		adapter 5 were in use in the worth west steeping room.							
10 16037			opet remnants were stored ag						

1 16.03.22.405.01.6 Electrical Equipment: Entensini cood and multiple cutlety

Glapter's were in use in the worth west steeping room,

Joensel B Secondary means of gream from steeping

Low on the worth west side was partially obstructed

by a dresser

Jic dills held since Now mhe 2005.

Jic dills held since Now mhe 2005.

Jic dills held since Now mhe 2005.

Jim 18.03.77.750.03 Fuel-Fired Hearting Inspection: A Copy of the required

annual inspection on the farmer has been mat legal on file

14.03.72.415.03 Portable fine Entenganghous Evidence or decommentation if

an annual professional inspection (and action the

brush of professional inspection of available to recover.

Colors 12.22.250.15 Vall System: Electronic wire less signalling was not

available from hoth hattercoms.

Response Required Date

Signature of Facility Representative

October 20, 2006